


IBEW

INTERNATIONAL
BROTHERHOOD OF
ELECTRICAL WORKERS
FOURTH DISTRICT

 1215-88
Kendall Advertising & Printing, Inc.



EDWIN D. HILL
International President

LINDELL K. LEE
International Secretary-Treasurer

SALVATORE (SAM) J. CHILIA
International Vice President
Fourth District

Corporate Plaza I • 6450 Rockside Woods Boulevard, South • Suite 150 • Independence, Ohio 44131 • (216) 328-0004 • Fax (216) 328-0444 • sam_chilia@ibew.org

May 26, 2009

TO: ALL CONSTRUCTION LOCALS

REFERENCE: SAFETY ISSUE – FLUKE METER WARNING

The Fourth District Office has been made aware of a very serious Safety Issue. Fluke has discovered a potential short circuit connection on the circuit board. This may lead to inaccurate voltage readings including a low or no voltage reading on a circuit energized with a hazardous voltage. This finding could create a hazardous situation if the user were to contact live voltage based on an erroneous instrument reading. Required Actions are as follows:

1. Stop using your affected 33X series clamp meter even if you have not experience problems.
2. Verify your clamp meter is affected using the serial numbers below.
Fluke – 337 (All models including 337A) Serial #96070000-09990607
Fluke – 336 (All models including 336A) Serial #96220000-98900400
Fluke – 335 (All models including 335A) Serial #97010000-98860104
Fluke – 334 (All models including 334A) Serial #97010000-98870101
Fluke – 333 (All models including 333A) Serial #97010000-98880240
3. Go to:
http://us.fluke.com/user/support/safetynote/33X_Recall/htm?trck=33xrecall and follow the directions provided or call (888) 98-FLUKE (35853) for more information.

Please advise your membership of this very important safety issue. The safety of every worker in the field is very important.

Fraternally,

Salvatore (Sam) J. Chilia
International Vice President
IBEW Fourth District